

STOP WORK ORDER

**ANY UNAUTHORIZED PERSON REMOVING THIS NOTICE WILL BE
PROSECUTED**

Permit #: PRRES20170812
Address: 1622 SW BLACKSTONE PL, LEES SUMMIT, MO 64082
Inspected On: 4/3/18
Inspected By: Matt Munger

Any person who shall continue work after having been served with a stop work order, except such work as that person is directed to perform to remove a violation or unsafe condition, shall be subject to penalties as prescribed by law.

Inspection: **Inspector:** **Outcome:** **Date:**

Comments:

Corrections have not been made to fix the issues with the Erosion Control that also has affected the neighboring yards.