LEE'S SUMMIT

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRRES20180307, Building Permit - Residential

Address: 1809 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Inspection		Inspector:	Outcome:	Date:
Erosion Control		Matt Munger	Failed	Tuesday, April 03, 2018
Corrective	Action Required			
	Matt Munger 04/03/2018 2:13 PM The ESC devices are not in compliance. The gravel and silt that has been tracked into the street will need to be removed.			

Comments: