

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRSUBD20180642, Development - Subdivision

PERGOLA PARK, 4TH PLAT

Address: 3200 SW PERGOLA PARK DR, LEES SUMMIT, MO 640811003 SW REDBUCK CIR, LEES SUMMIT,
MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Bob Burns	Passed	Wednesday, April 04, 2018

Informational

- 1 Tom Chandler 04/04/2018 2:20 PM No work going on today. ESC devices are installed and functioning properly. Will mulch trees when weater permits and use mulch as additional ESC devices.

Comments:
