



SW RAIN TREE PKWY



Pipe Graphic Report of PSR 62-208 X for 30155

Setup	7	Surveyor	jd	Certificate #	na	System Owner		
Drainage	MIDDLE BIG C	Survey Customer	30155					
P/O #		Date	2018/04/03	Time	13:39	Street	sw raintree pkwy	
City	lees summit	Further location details						
Up	62-208	Rim to invert		Grade to invert		Rim to grade	Ft	
Down	62-209	Rim to invert		Grade to invert		Rim to grade	Ft	
Use		Direction	Downstream	Flow control		Media No		
Shape		Height	8	Width	ins	Preclean	N	
Material		Joint length	Ft	Total length	201.5 Ft	Date Cleaned		
Lining		Year laid		Year rehabilitated		Length Surveyed	196.21 Ft	
Purpose				Cat		Weather		
Additional info						Structural	O & M	Constructional
Location						Miscellaneous	Hydraulic	
Project						Work Order 85933		
Northing						Easting		
Coordinate System						Elevation		
						GPS Accuracy		




PipeLogix Inc.  
 Phone: 866-299-3150  
 Fax: 760-406-6023



CCTV pictures of 62-208 X  
 For 30155

Work Order		Surveyed On 2018/04/03	
Street Name	sw raintree pkwy	Video	
City Name	lees summit	Weather	
Location			
From Manhole	62-208	To Manhole	62-209
		Survey Direction Downstream	

Setup 7 Counter 0.0 Ft



E:\Snaps\85933\12.jpg 2018/04/05

**Pipe Details:**

Year Laid	Shape	Size 8	By ins
Material	Lining	Use	

Observation: Code not found

Comments:




PipeLogix Inc.  
 Phone:866-299-3150  
 Fax:760-406-6023



CCTV pictures of 62-208 X  
For 30155

Work Order		Surveyed On 2018/04/03	
Street Name	sw raintree pkwy	Video	
City Name	lees summit	Weather	
Location			
From Manhole	62-208	To Manhole	62-209
		Survey Direction Downstream	

Setup 7 Counter 4.0 Ft



E:\Snaps\85933\13.jpg 2018/04/05

**Pipe Details:**

Year Laid	Shape	Size 8	By ins
Material	Lining	Use	

Observation: Code not found

Comments:




PipeLogix Inc.  
Phone:866-299-3150  
Fax:760-406-6023



CCTV pictures of 62-208 X  
For 30155

<b>Work Order</b>	<b>Surveyed On</b> 2018/04/03		
<b>Street Name</b> sw raintree pkwy			<b>Video</b>
<b>City Name</b> lees summit	<b>Weather</b>		
<b>Location</b>			
<b>From Manhole</b> 62-208	<b>To Manhole</b> 62-209	<b>Survey Direction</b> Downstream	

Setup 7 Counter 182.3 Ft



E:\Snaps\85933\14.jpg 2018/04/05

**Pipe Details:**

<b>Year Laid</b>	<b>Shape</b>	<b>Size</b> 8	<b>By</b> ins
<b>Material</b>	<b>Lining</b>	<b>Use</b>	

**Observation:** Code not found

**Comments:**




PipeLogix Inc.  
Phone:866-299-3150  
Fax:760-406-6023



CCTV pictures of 62-208 X  
 For 30155

Work Order		Surveyed On 2018/04/03
Street Name	sw raintree pkwy	Video
City Name	lees summit	Weather
Location		
From Manhole	62-208	To Manhole 62-209
		Survey Direction Downstream

Setup 7 Counter 190.2 Ft



E:\Snaps\85933\15.jpg 2018/04/05

**Pipe Details:**

Year Laid	Shape	Size 8	By ins
Material	Lining	Use	

Observation: Code not found

Comments:




PipeLogix Inc.  
 Phone:866-299-3150  
 Fax:760-406-6023



CCTV pictures of 62-208 X  
 For 30155

<b>Work Order</b>		<b>Surveyed On</b> 2018/04/03
<b>Street Name</b> sw raintree pkwy	<b>Video</b>	
<b>City Name</b> lees summit	<b>Weather</b>	
<b>Location</b>		
<b>From Manhole</b> 62-208	<b>To Manhole</b> 62-209	<b>Survey Direction</b> Downstream

**Setup 7**      **Counter** 190.2 Ft



E:\Snaps\85933\16.jpg 2018/04/05

**Pipe Details:**

<b>Year Laid</b>	<b>Shape</b>	<b>Size 8</b>	<b>By ins</b>
<b>Material</b>	<b>Lining</b>	<b>Use</b>	

**Observation:** Code not found

**Comments:**




PipeLogix Inc.  
 Phone:866-299-3150  
 Fax:760-406-6023



Pipe Graphic Report of PSR 62-207 X for 30155

Setup	8	Surveyor	jd	Certificate #	na	System Owner	
Drainage	MIDDLE BIG C	Survey Customer	30155				
P/O #		Date	2018/04/03	Time	11:33	Street	sw raintree plwy
City	lees summit	Further location details					
Up	62-207	Rim to invert		Grade to invert		Rim to grade	Ft
Down	62-208	Rim to invert		Grade to invert		Rim to grade	Ft
Use		Direction	Upstream	Flow control		Media No	
Shape		Height	8	Width	ins	Preclean	N
Material		Joint length	Ft	Total length	109.0 Ft	Date Cleaned	
Lining		Year laid		Year rehabilitated		Length Surveyed	102.07 Ft
Purpose				Cat		Weather	
Additional info				Structural      O & M      Constructional Miscellaneous      Hydraulic			
Location				Work Order 85933			
Project				Elevation			
Northing				Easting			
Coordinate System				GPS Accuracy			



PipeLogix Inc.  
 Phone: 866-299-3150  
 Fax: 760-406-6023



CCTV pictures of 62-207 X  
 For 30155

Work Order		Surveyed On 2018/04/03	
Street Name	sw raintree plwy	Video	
City Name	lees summit	Weather	
Location			
From Manhole	62-208	To Manhole	62-207
		Survey Direction Upstream	

Setup 8 Counter 0.0 Ft



E:\Snaps\85933\9.jpg 2018/04/05

**Pipe Details:**

Year Laid	Shape	Size 8	By ins
Material	Lining	Use	

Observation: Code not found

Comments:




PipeLogix Inc.  
 Phone:866-299-3150  
 Fax:760-406-6023



CCTV pictures of 62-207 X  
 For 30155

Work Order		Surveyed On 2018/04/03
Street Name sw raintree plwy	Video	
City Name lees summit	Weather	
Location		
From Manhole 62-208	To Manhole 62-207	Survey Direction Upstream

Setup 8 Counter 90.2 Ft



E:\Snaps\85933\10.jpg 2018/04/05

**Pipe Details:**

Year Laid	Shape	Size 8	By ins
Material	Lining	Use	

Observation: Code not found

Comments:



PipeLogix Inc.  
 Phone: 866-299-3150  
 Fax: 760-406-6023



CCTV pictures of 62-207 X  
 For 30155

Work Order		Surveyed On 2018/04/03
Street Name sw raintree plwy	Video	
City Name lees summit	Weather	
Location		
From Manhole 62-208	To Manhole 62-207	Survey Direction Upstream

Setup 8 Counter 100.0 Ft



E:\Snaps\85933\11.jpg 2018/04/05

**Pipe Details:**

Year Laid	Shape	Size 8	By ins
Material	Lining	Use	

Observation: Code not found

Comments:




PipeLogix Inc.  
 Phone:866-299-3150  
 Fax:760-406-6023



Pipe Graphic Report of PSR 64-167 X for 30155

Setup	5	Surveyor	jd	Certificate #	na	System Owner		
Drainage	MIDDLE BIG C	Survey Customer	30155					
P/O #		Date	2018/04/04	Time	12:26	Street	sw raintree pkwy	
City	lees summit	Further location details						
Up	64-167	Rim to invert		Grade to invert		Rim to grade	Ft	
Down	64-168	Rim to invert		Grade to invert		Rim to grade	Ft	
Use		Direction	Upstream	Flow control		Media No		
Shape		Height	8	Width	ins	Preclean	N	
Material		Joint length	Ft	Total length	300.9 Ft	Date Cleaned		
Lining		Year laid		Year rehabilitated		Length Surveyed	296.38 Ft	
Purpose				Cat		Weather		
Additional info						Structural	O & M	Constructional
Location						Miscellaneous	Hydraulic	
Project						Work Order 85933		
Northing						Easting		
Coordinate System						Elevation		
						GPS Accuracy		




PipeLogix Inc.  
 Phone: 866-299-3150  
 Fax: 760-406-6023



CCTV pictures of 64-167 X  
For 30155

Work Order	Surveyed On 2018/04/04		
Street Name sw raintree pkwy	Video		
City Name lees summit	Weather		
Location			
From Manhole 64-168	To Manhole 64-167	Survey Direction Upstream	

Setup 5 Counter 171.0 Ft



E:\Snaps\85933\17.jpg 2018/04/05

**Pipe Details:**

Year Laid	Shape	Size 8	By ins
Material	Lining		Use

Observation: Code not found

Comments:




PipeLogix Inc.  
Phone:866-299-3150  
Fax:760-406-6023



CCTV pictures of 64-167 X  
 For 30155

Work Order		Surveyed On 2018/04/04	
Street Name	sw raintree pkwy	Video	
City Name	lees summit	Weather	
Location			
From Manhole	64-168	To Manhole	64-167
		Survey Direction Upstream	

Setup 5 Counter 238.0 Ft



E:\Snaps\85933\18.jpg 2018/04/05

**Pipe Details:**

Year Laid	Shape	Size 8	By ins
Material	Lining		Use

**Observation:** Code not found

**Comments:**




PipeLogix Inc.  
 Phone:866-299-3150  
 Fax:760-406-6023



CCTV pictures of 64-167 X  
For 30155

Work Order	Surveyed On 2018/04/04		
Street Name sw raintree pkwy	Video		
City Name lees summit	Weather		
Location			
From Manhole 64-168	To Manhole 64-167	Survey Direction Upstream	

Setup 5 Counter 244.0 Ft



E:\Snaps\85933\19.jpg 2018/04/05

**Pipe Details:**

Year Laid	Shape	Size 8	By ins
Material	Lining	Use	

Observation: Code not found

Comments:




PipeLogix Inc.  
Phone:866-299-3150  
Fax:760-406-6023



CCTV pictures of 64-167 X  
 For 30155

Work Order		Surveyed On 2018/04/04
Street Name	sw raintree pkwy	Video
City Name	lees summit	Weather
Location		
From Manhole	64-168	To Manhole 64-167
		Survey Direction Upstream

Setup 5 Counter 286.5 Ft



E:\Snaps\85933\20.jpg 2018/04/05

**Pipe Details:**

Year Laid	Shape	Size 8	By ins
Material	Lining		Use

Observation: Code not found

Comments:




PipeLogix Inc.  
 Phone:866-299-3150  
 Fax:760-406-6023



CCTV pictures of 64-167 X  
 For 30155

<b>Work Order</b>		<b>Surveyed On</b> 2018/04/04
<b>Street Name</b> sw raintree pkwy	<b>Video</b>	
<b>City Name</b> lees summit	<b>Weather</b>	
<b>Location</b>		
<b>From Manhole</b> 64-168	<b>To Manhole</b> 64-167	<b>Survey Direction</b> Upstream

**Setup 5**      **Counter** 286.5 Ft



E:\Snaps\85933\21.jpg 2018/04/05

**Pipe Details:**

**Year Laid**                      **Shape**                      **Size 8**                      **By** ins

**Material**                      **Lining**                      **Use**

**Observation:** Code not found

**Comments:**




PipeLogix Inc.  
 Phone:866-299-3150  
 Fax:760-406-6023



CCTV pictures of 64-167 X  
 For 30155

<b>Work Order</b>		<b>Surveyed On</b> 2018/04/04
<b>Street Name</b> sw raintree pkwy	<b>Video</b>	
<b>City Name</b> lees summit	<b>Weather</b>	
<b>Location</b>		
<b>From Manhole</b> 64-168	<b>To Manhole</b> 64-167	<b>Survey Direction</b> Upstream

**Setup 5**      **Counter 286.5 Ft**



E:\Snaps\85933\22.jpg 2018/04/05

**Pipe Details:**

Year Laid	Shape	Size 8	By ins
Material	Lining	Use	

**Observation:** Code not found

**Comments:**



PipeLogix Inc.  
 Phone:866-299-3150  
 Fax:760-406-6023