
PUBLIC WORKS ENGINEERING DIVISION

Field Engineering Inspections Site Visit

Permit #: PRPWLD20172188, Public Works Land Disturbance Permit
Browning Property Borrow Area
Address: 1745 SE HAMBLER RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Erosion Sediment Control (ESC) Inspection Informational 1	Troy Thompson	Partial	Friday, April 13, 2018
ESC was in compliance.			

Comments:
