LEE'S SUMMIT

## PUBLIC WORKS ENGINEERING DIVISION

## **Inspection Summary**

Permit #: PRPWFC20173845, Public Works Infrastructure Permit - Commercial Scooters coffee

Address: 805 SW M 150 HWY, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item: Inspection: Inspector: Outcome: Date:					
inspec		inspector.	Outcome.	Date.	
DE-ESC - (Vegetation/Ground Cover)		Matt Munger	Partial	Monday, April 23, 2018	
	, tive Action Required			, (pril 20) 2020	
1	Matt Munger 03/12	/2018 8:17 AM			
-	East side of the prop	East side of the property will need to have vegetation established. Sod has been installed througout the rest of the site.			
Inform	national				
2	Matt Munger 03/20/2018 12:38 PM				
	Erosion control devices have been removed and sod was installed. Sheldon is going to hydra seed the disturbed area on the east.				
Inform	national				
3	Matt Munger 03/21/2018 3:45 PM				
	The disturbed soil on the east side on the vacant lot has been hydro seeded.				
Inform	national				
4	Matt Munger 04/03/2018 2:42 PM				
	It appears the hydro few spots.	seed that was applie	d to the vacant lot to the e	ast has washed off in a	
Inform	national				
5	Matt Munger 04/13	/2018 10:00 AM			
	Grass has started to grow on the vacant lot.				
Inform	national				
6	Matt Munger 04/18	/2018 1:40 PM			
	Grass has started to grow on the vacant lot, but there is not enough vegetation established at this time.				
Inform	national				
7	Matt Munger 04/23	/2018 10:03 AM			
	Some grass has start	ed to grow but there	is still a larger area of bare	soil that will need to	

be vegetated on the vacant lot.

Comments: