

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRSUBD20180158, Development - Subdivision
Park Ridge 6th Plat

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

| Inspection: | Inspector: | Outcome: | Date: |
|---|---|----------|----------------------------|
| DEI-Grading/Excavation/Fill Inspection Informational | Jeremy Young | Partial | Tuesday, April 24, 2018 |
| 1 | Jeremy Young 04/19/2018 3:23 PM Crew has begun the mass grading on the site. They are working on the north side of the site adding dirt. | | |
| Informational | | | |
| 2 | Jeremy Young 04/20/2018 9:47 AM John DiMauro and I were on site. The crew is still grading and filling around the site. | | |
| Informational | | | |
| 3 | Jeremy Young 04/23/2018 11:10 AM Crew is mass grading the site for streets. | | |
| Informational | | | |
| 4 | Jeremy Young 04/24/2018 1:33 PM Crew is continuing the mass grading on the site today. They are working on the east and north side of the property. | | |

Comments: