

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRSUBD20180158, Development - Subdivision
Park Ridge 6th Plat

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Water - Material Verification Informational	Jeremy Young	Partial	Monday, April 30, 2018

- 1 Jeremy Young 04/30/2018 11:02 AM The crew had water supplies delivered this morning. The pipe delivered is C-900. The pipe has been manufactured within the last year. The gate valves are American Corp 2508 8" valves. The tracer wire is 12 Gage wire. The 8x8 Tee is Star MJ-8.

Comments: