

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFR20161876, Public Works Infrastructure Permit - Residential
Napa Valley 3rd Plat Street/Storm/MDP/ESC, sanitary sewer

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Public Curb Inspection	Matt Munger	Failed	Friday, May 11, 2018

Corrective Action Required

1 Matt Munger 05/11/2018 11:22 AM

John D. and I went throught to check for any damage to the curbs.

- Lot 129 (SW Blackstone PL.) there was a crack in the curb.

- 1522 SW Blackstone PL. there was a crack in the curb.

- At the corner of SW Blackstone PL. & SW Napa Valley Dr. close to the lot 128 there are two cracks.

- At the corner of SW Meritime Cir. by lot 114 there is a crack in the curb..

- 4012 SW Meritime Cir. there is a crack in the curb.

- At the corner of SW Stoneybrook Dr. & SW Blackstone PL. by closest to the fire hydrant there is a crack in the curb.

See attached pictures for proof of damage to curb.

Comments: