

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Address: 3352 SW JESSIE LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:
Inspection:

Inspector:

Outcome:

Date:

DEI-Sidewalk Inspection

John DiMauro

Partial

Thursday,

May 24, 2018

Informational

1 John DiMauro 05/24/2018 2:25 PM

Permit #: PRRES20170715, Building Permit - Residential

The froms are up and the rock is compacted. I asked Bill not to tie the new sidewalk into the existing due to the existing sidewalk being out of compliance.

Comments: