

Certificate of Occupancy

Permit #: PRRES20163192
Address: 1329 NE BRANDYWINE RD, LEES SUMMIT, MO 64064
Inspected On: Wednesday, June 13, 2018
Inspected By: Khanh Nguyen

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	Khanh Nguyen Full C of O		Wednesday, June 13, 2018

Comments: