

Certificate of Occupancy

Permit #: PRCOM20180775
Address: 1196 NE DOUGLAS ST, LEES SUMMIT, MO 64086
Inspected On: Monday, June 18, 2018
Inspected By: John BornsJohn Borns

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - John Borns Codes Commercial	Full C of O		Monday, June 18, 2018
Hood/Duct Inspection John Borns	Passed		Monday, June 18, 2018

Comments: HOOD VELOCITY TEST REPORT RECEIVED & ACCEPTED. NO REMAINING ISSUES. OK FOR USE & OCCUPANCY.