

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFR20171420,

Address:

CREEKSIDE AT RAINTREE

Inspecti Inspect	on Item: ion: Inspector:	Outcome: Passed	Date: Monday, June 25, 2018
DEI-Wa 1 Informat	ter Line - Coliform Test Brice Lawson		
1	Brice Lawson 06/18/2018 3:13 PM		
	the newly isolated water main in this subdivision. This was due to the line not being pressurized after all the required bacterial samples had passed. Arron with Schleif Construction took 3 bacterial samples from the construction taps located in three different areas in the subdivision. One is near the end of the main in the south cul de sac, one is near the end of water line 1-1 and one is just north of STA. 4+78.70. I delivered the water samples to Blue Valley Lab at about 12:00pm.		
Informa	•	·	
2	Brice Lawson 06/25/2018 9:22 AM The bacterial tests passed.		
Comme	·		