

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Address: 1349 NE BRANDYWINE RD, LEES SUMMIT, MO 64064

Permit #: PRRES20173427, Building Permit - Residential

Comments:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

once all c	orrective actions ha	ive been completed. Do	not cover any work until a	approved.
Inspection Item: Inspection:		Inspector:	Outcome:	Date:
DEI-Sidewalk Inspection		Jeremy Young	Partial	Wednesday, June 27, 2018
Information 1	Jeremy Young 06/27/2018 2:14 PM Contractor has sufficient compacted rock. the cross slope is less than 2% which meets ADA requirements.			
,	Inspection	Jeremy Young	Partial	Wednesday, June 27, 2018
Information 1	onal Jeremy Young 06/27/2018 2:17 PM Contractor has torn out the drive approach. They have less than 2% cross slope which meets ADA compliance. They have the expansion joint and will add it.			