

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20181482, Building Permit - Residential
Address: 619 NE LONE HILL DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Footing Inspection - Residential	Khanh Nguyen	Not Ready	Thursday, June 28, 2018

Corrective Action Required
1 Misc **see erosion control

Erosion Control	Khanh Nguyen	Failed	Thursday, June 28, 2018
------------------------	--------------	--------	-------------------------

Corrective Action Required
1 DCM5 Erosion Control REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION CONTROL INSTALLATION.

**INSTALL EROSION CONTROL AROUND LOT AND GRAVEL FILTER BED AT LOT ENTRANCE

Comments: