

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

| Address: | | | | |
|-----------------------------|-------------------------------|-----------------|--------------------|-----------|
| This work has been inspecte | ed and the inspection results | noted below. Pl | ease call for re-i | nspection |

Permit #: PRSUBD20180158, Development - Subdivision

Park Ridge 6th Plat

Inspection Item:

Inspection: Outcome: Date:

once all corrective actions have been completed. Do not cover any work until approved.

DEI-Public Curb Inspection Steve Robbins Partial Thursday,

July 12, 2018

Informational

There is no one here today, I still need to get the core sample results back for the curbs. They are also going to come back and grout the honeycomb areas. Steve Robbins 07/12/2018 9:08 AM

Comments: