

Inspection Summary

Permit #: PRRES20180854, Building Permit - Residential
Address: 4720 NE GATEWAY DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Gas Service Inspection - Residential	Khanh Nguyen	Passed	Wednesday, July 25, 2018

All Rough Inspection - Residential	Khanh Nguyen	Failed	Wednesday, July 25, 2018
---	--------------	--------	--------------------------

Corrective Action Required

1 Misc

AT THE BIG LVL BEAM POINT LOAD RIGHT NEXT TO THE MAIN RETURN AIR DUCT (ACROSS FROM THE STAIR), ADD FULL SUPPORT STUDS DOWN TO THE GRADE BEAM BELOW IN BASEMENT. CHECK THE PLAN

****OK TO ROCK**

Comments: