

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRSUBD20180348	8, Development - Subdivision
Manor at Stoney	Creek 3rd Plat

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:
Inspection:
Inspector:
Outcome:
Date:

DEI-Sanitary Sewer
Brice Lawson
Partial
Monday, July
Construction Inspection
Informational

Brice Lawson 07/30/2018 8:27 AM
On 7/27/18 Redford Construction informed me that they installed 56' of 8" sanitary main from MH-10 to the south. It appeared that the sanitary main is being bedded with clean rock. They were backfilling the road crossing in just south of MH-10. KC Testing was on site and let me know that compaction test results for the trench backfill are all within spec.

Comments: