

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20181674, Building Permit - Residential

Address: 1613 SW MERRYMAN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mike Copeland	Failed	Monday, August 06, 2018

Corrective Action Required

- | | | |
|---|------|--|
| 2 | Misc | <ul style="list-style-type: none">• Sill plate needs anchor at deck corner 12" from butt ends• Strap top plate at sw corner of garage at splice• Fire block at hole next to floor outlet in great room• No Thermopylae at shower per plans• Fire block at rear entry door sill plate• Strap top plate at nw front bedroom• No brace wall within 10' of corner at rear master bed |
| | | have engineer address |
| | | <ul style="list-style-type: none">• Fire stop area around plumbing at southwest corner• basement• |

Comments: