

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRSUBD20180796, Development - Subdivision Hawthorn Ridge 1st Plat - onsite Address:			
	k has been inspected and the inspection rescorrective actions have been completed. Do		
Inspectio		Outcome:	Date:
DEI-Wate	er Line - Coliform Test Tom Chandler	Passed	Thursday, August 03, 2018
Information 1	onal Day 2 samples passed. Contractor to tie-in	water main next week.	
Taps Ren		Passed	Thursday, August 09, 2018
Information 1	onal Construction taps removed and repair clar Tested under pressure to check for leaks.	mps supplied by water utili	ties were installed.
DEI-Water Line - Construction Tom Chandle Inspection		Passed	Thursday, August 07, 2018
Information 1	Contractor performed tie-in to existing water main. All test have passed and emailed lab results to water utilities. Line was flushed after tie-in was completed.		
Commen	ts:		