

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #: PRRES20181168, Building Permit - Residential

Address: 1313 NE BRANDYWINE RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item: Inspection:		Inspector:	Outcome:	Date:	
Driveway Inspection		John Jackson	Passed	Tuesday, August 28, 2018	
Corrective	e Action Required				
1	The legal description, including plat or phase number and lot number, and street address must be provided on the plot plan.				
**Revise the street name to NE Brandywine Rd in plan view.**  Corrective Action Required  Property boundary distances and bearings, as shown on the recorded plat, must be					
	provided on the plot plan.				
	**The rear property	line distance per plat is 92.7	1', remove the extra 91.30'	dimension.**	
	***Revise the east p	property line bearing from S &	& W to N & E to match the p	lat.***	
DEI-Sidewalk Inspection		John Jackson	Passed	Tuesday, August 28, 2018	

## Informational

John Jackson did this for me, the sidewalk was formed the rock was installed and compacted and everything appeared to be up to standard. Steve Robbins 08/20/2018 3:55 PM

## Informational

2 Meets specification John Jackson 08/28/2018 12:05 PM Informational

3	Meets spec.John Jackson 08/28/2018 12:11 PM
Correcti	ve Action Required
4	
Comme	nts: