

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Address:					
This work has been	inspected and the	e inspection res	ults noted below.	Please call for r	e-inspection

once all corrective actions have been completed. Do not cover any work until approved.

Permit #: PRSUBD20180796, Development - Subdivision Hawthorn Ridge 1st Plat - onsite

Inspection Item:
Inspection:

Inspector:

Outcome:

Date:

Del-Stabilized Subgrade

Tom Chandler

Partial

Wednesday,
September
05, 2018

Informational

1 Tom Chandler 09/05/2018 1:41 PM 9" stabilized subgrade installed on Arboridge drive.

Comments: