

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20180778, Building Permit - Residential
Address: 1849 SW BLACKSTONE CT, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Gas Service Inspection - Residential	Jason McRoy	Passed	Tuesday, September 18, 2018

Electrical Service Inspection - Residential	Jason McRoy	Passed	Tuesday, September 18, 2018
--	-------------	--------	-----------------------------

All Rough Inspection - Residential	Jason McRoy	Failed	Tuesday, September 18, 2018
---	-------------	--------	-----------------------------

Corrective Action Required

- | | | |
|---|------|--|
| 1 | Misc | <ul style="list-style-type: none">garage portal not nailed per code 3" ocAdd anchor bolts at 12 " from splice ends and butt ends of sill plate in garageComplete fire blocking above fireplaceFire block at closet front bedroom 1st flVent exhaust fan in guest shower 1st flTriple joist under stairs is over notched northeast wall in basementAdd nailer at steel beam at south west bedroom in basementTape heat ac duct at southwest bedroom in basementConnect bath fan vent west side of basement |
|---|------|--|

Gas Piping Inspection -	Jason McRoy	Passed	Tuesday, September 18, 2018
--------------------------------	-------------	--------	-----------------------------

Residential

Comments: