

---

**PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

---

Permit #: PRRES20181381, Building Permit - Residential

Address: 4431 SW AMETHYST DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection Item:

<b>Inspection:</b>	<b>Inspector:</b>	<b>Outcome:</b>	<b>Date:</b>
Driveway Inspection	Joe Starlin	Partial	Thursday, September 20, 2018

Informational

- 1 Joe Starlin 09/20/2018 7:10 AM The driveway was inspected aggregate was compacted and at correct depth. Ready to be poured.

**Comments:**

---