

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

Permit #: PRRES20181381, Building Permit - Residential

Address: 4431 SW AMETHYST DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Driveway Inspection	Joe Starlin	Partial	Thursday, September 20, 2018
Informational			
1	Joe Starlin 09/20/2018 7:10 AM The driveway was inspected aggregate was compacted and at correct depth. Ready to be poured.		
DEI-Sidewalk Inspection	Joe Starlin	Partial	Thursday, September 20, 2018
Informational			
1	Joe Starlin 09/20/2018 7:14 AM The sidewalk was inspected aggregate was compacted and forms are in spec. Sidewalk is ready for concrete.		

**Comments:**