Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20181672, Building Permit - Residential Address: 4411 SW AMETHYST DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date: Inspector: **Gas Piping Inspection -** Mike Copeland Thursday, September 20, 2018 Passed Residential **Electrical Service** Mike Copeland Passed Thursday, September 20, 2018 **Inspection - Residential** All Rough Inspection -Mike Copeland Failed Thursday, September 20, 2018 Residential

Corrective Action Required

1 Misc -SUPPLY DUCT OVER LIVING WINDOWS DOESN'T FIT IN FUR.

-VENT KITCHEN SINK CORRECTLY -SECURITY BLOCK REAR DOOR

-SHIM 2ND FLOOR TRIMMER STUDS FOR FULL BEARING. -2ND FLOOR HALL, ADDITIONAL RECEPTACLE REQUIRED

-MASTER BATH VENT MISSING FLASHING

Gas Service Inspection - Mike Copeland Failed Thursday, September 20, 2018 **Residential**

Corrective Action Required

1 Misc MAX 30 POUND GUAGE FOR PRESSURE TEST

Comments: