

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRRES20181676, Building Permit - Residential

Address: 4423 SW AMETHYST DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Driveway Inspection	Joe Starlin	Partial	Friday, September 21, 2018
Informational			
1	Joe Starlin 09/21/2018 3:10 PM The driveway approach has been inspected, aggregate was compacted and the forms are set.		
DEI-Sidewalk Inspection	Joe Starlin	Partial	Friday, September 21, 2018
Informational			
1	Joe Starlin 09/21/2018 3:50 PM Inspected the sidewalk, aggregate was compacted and forms set.		

Comments: