

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20181743, Building Permit - Residential

Address: 4709 NE POCONO CIR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|---|--------------|----------|-----------------------------|
| All Rough Inspection - Residential | Khanh Nguyen | Failed | Wednesday, October 03, 2018 |

Corrective Action Required

| | | |
|---|------|---|
| 1 | Misc | -Strap CSPF wall at rear dining and entry per plan; nail sheathing per plan |
|---|------|---|

****PLEASE LOOK AT PAGE D4 OF THE PLAN. THE PICTURE DETAIL SHOWS EXACTLY HOW THE CS-PF IS FRAMED. SEE HOW THE STRAPS EXTEND ALL THE WAY TO THE TOP PLATES? ALSO NOTICE THE LOCATION OF THE STRAPS? IT'S ON THE INNER SIDE NEXT TO THE WINDOW. SEE THE NAILING PATTERN?**

Comments: