

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRSUBD20162865,	Development - Subdivis	sion	
Address:			
This work has been inspecte once all corrective actions ha	•		-
Inspection Item: Inspection:	Inspector:	Outcome:	Date:
DEI-Storm - Pipe	John Jackson	Partial	Friday, October 05, 2018
boxes. Installed sto		tor poured invert for newl 14 30' feet of 15" HDPE an installed.	•
DEI-Water Line - Construction	on John Jackson	Partial	Friday, October 05, 2018
Informational Contractor comple plans.	eted water line installati	on for 8' water line piping	for Street Crossing per
DEI-Storm - Pipe		Partial	Friday, October 05, 2018
Comments:			