Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20181851, Building Permit - Residential Address: 1531 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
Gas Service Inspection - Residential	Jason McRoy	Passed	Wednesday, October 10, 2018	
All Rough Inspection - Residential	Jason McRoy	Failed	Wednesday, October 10, 2018	
Corrective Action Require	۰d			
1 Misc • • missed •		Add anchor bolt at v d plate Add anchors within ide of garage Add anchors at sout Add anchor at north Complete fir out in g	Add anchors within 12 " of splices in bottom plate on of garage Add anchors at south side bottom plate in garage Add anchor at northeast portal Complete fir out in garage and firestop Add joist hangers where joist is headered off in flex	
	heade			
	• report •	Strap top plate at no ws in dining room Cut double lvl in ma Complete snow bloo	de of fir out at range orth wall right and left of ster bedroom provide engineers cking in master bedroom on	
	south • • splice	Anchor all steel sup Security blocking at	port posts in basement basement egress door south side of stairs within 12″ of	

- Anchor sill plate at south wall right of triple windows
- Tighten nut at plate anchor at north west corner of basement
- Is all joist hangers to header at cut joist in basement and repair hole in floor sheathing.

Electrical ServiceJason McRoyPassedWednesday, October 10, 2018Inspection - Residential

Comments: