



DEVELOPMENT SERVICES

Inspection Summary

Permit #:PRRES20181393, Building Permit - Residential
Address: 1829 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Jason McRoy	Failed	Tuesday, October 23, 2018

Corrective Action Required

- | | | |
|---|------|--|
| 2 | Misc | <ul style="list-style-type: none">• fire block spaces left and right of fireplace from fireplace space• Exhaust all bath fans on main floor• Connect gas line at fireplace• Fire block entire east wall in basement from joist space from back of the house to the panel• Exhaust all bath fans in basement• Fire block entire west wall in basement from joist space from back of house to front• Fire block south wall at sliding glass doors in basement from fir down space• Fire block north wall from fir down space in basement at fir down left of stairs• Fire stop gap at north wall basement• Fire block left of windows in basement at fir down• No lags or ledger locks at deck•• |
|---|------|--|

Comments: