## **CITY OF LEE'S SUMMIT**

# Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

# **Inspection Summary**

Permit #:PRRES20181846, Building Permit - Residential Address: 1301 NE GOSHEN DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Wednesday, October 24, 2018

Residential

### Corrective Action Required

1 Misc FRAMING:

- -Strap garage portal brace wall header per code; install 2" washers
- -Anchor sill plate within 12" of breaks
- -Strap cut top plate at garbage&entry wall intersection
- -The wall between the front bedrooms is not a bearing wall.

Support roof per plan

- -Strap across cut wall top plates at front bedroom
- -Fb fireplace space from roof; Fb basement wall from ceiling fur-down space
- -Stud cut off at basement wet bar
- -Solid block joist ends above basement I beam
- -Seal penetrations of ceiling joist return air space
- -Solidblock underneath triple 18" LVL point load at rear end

### ELECTRICAL:

- -Move the master bed smoke alarm min 3 ft from fan blade
- -Complete wiring to living room wall receptacle
- -Protect wiring at living room rear wall bottom plate
- -Secure SE cable within 12" of meter enclosure
- -Fasten the wiring min 1.25" away from nailing surface along the stud near bottom stair landing
- -Complete wiring to basement wall receptacle and ceiling outlets

-Bond gas piping

### PLUMBING:

- -Install stud shoes for studs bored more than 60% at basement bathroom
- -Bend the CSST gas line away from damage at rear basement bed ceiling.

\*\*OK TO INSULATE

**Comments:**