Inspection Summary

Permit #: PRRES20180333, Building Permit - Residential

Address: 1607 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item: Inspection:		Inspector:	Outcome:	Date:	
DEI-Sidev	valk Inspection	Joe Starlin	Passed	Thursday, November 08, 2018	
Corrective Action Required					
1 Information	The sidewalk has been inspected and after aggregate and form adjustments it is in spec. Ready for pour. Informational				
2	Inspected sidewalk and it has met the spec.Joe Starlin 11/08/2018 7:39 AM				
DEI-Sidev	valk Inspection	Joe Starlin	Passed	Thursday, November 08, 2018	
Informational					
1	The sidewalk has been inspected and after aggregate and form adjustments it is in spec. Ready for pour.				
Informational					
2 Joe Starlin 11/08/2018 7:11 AM The sidewalk has been inspected and meets spec.					

Comments: