| Inspection Summary Permit #: PRSUBD20182996, Development - Subdivision | | | |
|---|--|--|---------------------------------|
| | | | |
| This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved. | | | |
| Inspection Item: Inspection: | Inspector: | Outcome: | Date: |
| DEI-Sanitary Sewer Construction Inspection | Joe Starlin | Partial | Friday, Novembei 16, 2018 |
| | they bored under Victo ary pipe and back filled | ria RD and installed sanitary 90.51 LF from A1 to A2. | sewer. 11/15/18 |
| DEI-Sanitary Sewer Construction Inspection | Joe Starlin | Partial | Friday, Novembei 16, 2018 |
| | /2018 3:29 PM The crew nen installed one 45 ft la | placed 130.17 LF sanitary p teral run. | |
| Comments: | | | |