

Inspection Summary

Permit #: PRSUBD20162865, Development - Subdivision

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
DEI-Curb - Proof Roll	John Jackson	Passed	Friday, November 16, 2018

Informational

1

Proof roll passed inspection areas of concern dried out with rising temperatures 11/15/16. Ticket # 2324459 was taken for the Dump Truck used to proof roll John Jackson 11/16/2018 3:38 PM

Comments: