

Inspection Summary

Permit #: PRSITE20171570, Development - Site
CONTROL SERVICES

Address: 3621 NE AKIN DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DE-ESC - (Vegetation/Ground Cover)	Steve Robbins	Partial	Monday, November 19, 2018

Informational

1 None of the vegetation has been installed or established yet. Steve Robbins 08/24/2018 2:29 PM

Informational

2 No sod or vegetation has been installed yet. Steve Robbins 08/30/2018 2:48 PM

Informational

3 The contractors have been working on the landscaping but they have not put in any vegetation yet. Steve Robbins 10/05/2018 2:45 PM

Informational

4 The landscaping and the sod for around the building has been installed. The contractors have installed seed and straw throughout the site in the back of the building. I will check back in March to check the progress of the grass coming in. Steve Robbins 11/19/2018 12:43 PM

Comments: