

Inspection Summary

Permit #: PRSITE20180219, Development - Site
MERIDIAN AT VIEW HIGH APARTMENTS
Address: 201 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Stabilized Subgrade	Steve Robbins	Partial	Monday, November 26, 2018

Informational

- 1 The contractors from Bair Excavating have been installing geo-grid and rock for the private road and parking spaces on this site. The have it installed up to apt. 5 and are working their way down to apt. 8 and 9. Steve Robbins 11/09/2018 1:24 PM

Informational

- 2 The contractors from Bair have installed the geo-grid and rock for the parking lot up to building 5 on both sides.

Comments: