

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20182431
Address: 4426 SW AMETHYST DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Jason McRoy	Failed	Wednesday, November 28, 2018

Corrective Action Required:

- | | | |
|---|------|--|
| 2 | Misc | <ul style="list-style-type: none">• add 2 studs at steel beam in garage and move outside outlet to accomadate studs.• Strap top plate in southeast corner of garage• Fire block at heat flue 2nd fl. Where pan ends around plumbing vent stack., and above heat vent. Block stud space.• Flexible duct work is resting on top of can light fixture in master bath water closet• Fire stop all unused electrical penetrations on 2nd fl |
|---|------|--|

Comments: