	Inspection	Summary	
Permit #: PRSUBD20162865, [Development - Subdiv	sion	
Address:			
This work has been inspected once all corrective actions hav	<u>=</u>		
Inspection Item: Inspection:	Inspector:	Outcome:	Date:
DEI-Water Line - Fire Hydrant	John Jackson	Partial	Wednesday, December 05, 2018
Informational 1 Hydrants installed @	9 Sta 1+57.50 & 5+85.	47. John Jackson 12/05/201	.8 9:25 AM
DEI-Water Line - Construction Inspection	John Jackson	Partial	Wednesday, December 05, 2018
Informational 1 Contractor installed Jackson 12/05/2018		/C from sta 1+25 to Sta 6+00	
DEI-Grading/Excavation/Fill Inspection	John Jackson	Partial	Wednesday, December 05, 2018
Informational 1 Contractor began gr 12/05/2018 9:49 AN		rature above 30 degrees. Jo	hn Jackson
DEI-Water Line - Construction Inspection	John Jackson	Partial	Wednesday, December 05, 2018
Informational			03, 2010

1	Contractor secured installation of fire hydrants on line 9 and installed approximately 200' of 8" C-900 Class 200 PVC Water Main on Line 8 From 0+30 to 2+00. John Jackson 12/05/2018 4:01 PM
Comm	ents: