Inspection Summary			
	52865, Development - Subdivi	sion	
Address:			
	spected and the inspection resions have been completed. Do		· · · · · · · · · · · · · · · · · · ·
Inspection Item:			
Inspection:	Inspector:	Outcome:	Date:
DEI-Water Line - Cons Inspection	truction John Jackson	Partial	Monday, December 10, 2018
Contractor h	nstalled approximately 500' of nas he intial installation of water r		ter main on Line 6.
DFI-Water Line - Fire I	Hydrant John Jackson	Partial	Monday, December 10, 2018
DEI Water Eine The			-,