

Inspection Summary

Permit #: PRSITE20180219, Development - Site
MERIDIAN AT VIEW HIGH APARTMENTS
Address: 201 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Stabilized Subgrade	Steve Robbins	Partial	Tuesday, December 11, 2018

Informational

1 The contractors from Bair Excavating have been installing geo-grid and rock for the private road and parking spaces on this site. The have it installed up to apt. 5 and are working their way down to apt. 8 and 9. Steve Robbins 11/09/2018 1:24 PM

Informational

2 The contractors from Bair have installed the geo-grid and rock for the parking lot up to building 5 on both sides.

Informational

3 The have now installed rock and geo-grid up to building 11 and 12. It needs to cure out. Steve Robbins 12/11/2018 8:26 AM

Retaining Wall Inspection	Steve Robbins	Partial	Tuesday, December 11, 2018
---------------------------	---------------	---------	----------------------------------

Informational

1 The retaining wall on the west and north sides of the property has been completed. PSI has been doing testing for the sight. Steve Robbins 11/01/2018 8:41 AM

Informational

2 They have all the retaining walls up for the buildings 1-7 in that area. PSI has been out testing for the retaining walls. Steve Robbins 12/11/2018 8:14 AM

Comments:

