



DEVELOPMENT SERVICES

Inspection Summary

Permit #: PRSUBD20162865, Development - Subdivision

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
DEI-Subgrade Inspection	Steve Robbins	Partial	Tuesday, October 23, 2018

Informational
1 Misc

Spalding is installing fly -ash for the subgrade. They are using a tiller and a water truck for the installation of the fly-ash. Olsen has been on site doing the testing. Steve Robbins 10/23/2018 7:38 AM

Comments: