Inspection Summary Permit #: PRSUBD20162865, Development - Subdivision				
This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.				
nspection Item: Inspection:		Inspector:	Outcome:	Date:
DEI-Street - Bas	e Lift	John Jackson	Partial	Thursday, December 13, 2018
all stro sched	eet. Secon	d base layer of asphalt is r second base layer on (Jam	mpleted laying the first bas equired on (Jamestown Dri estown Drive) and surface I	ve). Tentative
Comments:				