

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20181672
Address: 4411 SW AMETHYST DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	Jason McRoy	Failed	Friday, December 14, 2018

Corrective Action Required:

2	Misc	Panel gfi is not wired correctly no power to outlet at sub panel * NORTHEAST SIDE OF FRONT PORCH IS OVER 30" AFTER FINAL GRADING. WILL REQUIRE A GUARD RAIL. * SOD
---	------	--

Comments: