Inspection Summary				
Permit #	: PRSUBD20182	996, Development - Subdiv	vision	
Address	: 1410 NE DOUG	GLAS ST, LEES SUMMIT, MO	64086	
once all	corrective action		esults noted below. Please ca o not cover any work until a	· · · · · · · · · · · · · · · · · · ·
Inspection Item: Inspection:		Inspector:	Outcome:	Date:
DEI-Site	Visit	Joe Starlin	Partial	Tuesday, December 18, 2018
Informat			t Oak View job site at 8am. E	
1 Informa	permit to Brad forward.	dley O'Connor. We reviewe	u pians and discussed a gam	c pian
1 Informa 2 Informa	permit to Brad forward. tional 8:30am 12/13 Brad O'Conno		ivered and went over plans	