

■ KRUGER TECHNOLOGIES, INC. ■

REPORT OF SPECIAL INSPECTION

Client: John Knox Village **Address:** 602 NW Pryor Road
Lee's Summit, MO 64081

Project: JKV Village Assisted **Project Number:** 218185C.004
Living 400 Unit

Date Tested: 11/29/2018 **Date Reported:** 12/03/2018 **Technician:** DD

Associated Test: Nuclear Compactions 218185C.005

A KTI representative was on site to inspect the placement of structural backfill for the building pad. Backfill consisting of light brownish lean clay was placed in approximately 1.5' lifts and compacted with a roller. Six compaction tests were performed by nuclear method. Contractor was notified of test results.

Respectfully submitted,
KTI-Kruger Technologies, Inc.



for Otto J. Kruger, Jr., P.E.