CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20182092

Address: 1611 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mark Harding Failed Friday, December 28,

Residential 2018

Corrective Action Required:

1 Misc -plumbing protection plate east wall front bedroom .

-security blocking at sliding door, mstr bedroom door etc.

-firestop fireplace from attic over mstr, each side of firepalce over builtins.

-vent all bath fans and firestop penetrations.

-install rear slider.

-install floor box at rear great room.

-install floor outlets along stair opening per code.

-firestop dbl wall at star/ garage wall.

- fire stop dbl bsmt walls east side 10' horizontal.

- firestop over bsmt window NE bedroom from josit space.

- firestop bathroom at ceiling height with 3/4" or 2x4 material.

-plumbing protection plates NE bsmt bedroom at bath wall.

-anchor bsmt beam posts.

-firestop all tub shower traps.

- holes drilled in bottom 2" over josit over bar sink and NW bsmt bath.

Comments: