

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20183171
Address: 1630 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Jason McRoy	Failed	Wednesday, February 13, 2019

Corrective Action Required:

3	Misc	Fire stop nm electrical penetration left of radon chase in garage. Fire block fireplace to attic space. Fire stop gas line penetration at fireplace. Fire block top of great room wall opposite of laundry rm. fire block top of wall from master entry hall to return air space. Fire block stairway wall from mid stairs to front door. Support hip and valley above mudroom (purlin). Install boot at plumbing vent over master bath. Add strong backs to purlins throughout.
---	------	--

Comments: