CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRSITE20180252 Address: 1600 SE HAMBLEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: DEI-Sanitary Sewer Construction Inspection		Inspector:	Outcome:	Date:	
		John DiMauro	Partial	Tuesday, February 26, 2019	
Corrective Action Require 1 Misc		John DiMauro 11/30/2018	9:24 AM		
		On Tuesday 11/27/18 The city of Lee's Summit Water Utilities department performed a camera inspection on the public section of the sanitary sewer line.			
		Water Utilities identified active.	defects with the line and th	ne line appears to be	
		They identified that the service line is entering into the sewer main below the flow line and coming up into the pipe. Since the wye is coming up into the main, the service line is holding lots of waste and not properly draining into the main.			
		Another issue is the main lot of water.	that enters into the existin	g manhole is holding a	
		Please make the proper corrections to the sanitary service line.			
Informatio 2	onal: Miscellaneous Correction		crew is continuing the new wo 4" lines tied into the 6"	•	

		will continue the install and I will return for further inspection tomorrow 2/1/2019.
Informati	onal:	
3	Misc	The American Dirt Works crew has the 6" sanitary sewer line installed to approximately station 1+99.09
		The crew plans to backfill the installed section of line and continue the install next week. There appears to be sufficient aggregate surrounding the 6" pipe.
Informati	onal:	
4	Misc	The American Dirt Works crew installed the 6" line to the wye coming off the main.
Corrective	e Action Required:	
5	Miscellaneous Correction	
Informati	onal:	
6	Misc	Contractor Mike Fisher is on site working on the drop MH on the east side of Hamblen RD.
		The crew plans to make corrections to the drop in the next few. Days.
Informati	onal:	I will return for further inspection at a later date.
7	Misc	The crew finished the corrections to the drop manhole to get it to drain properly.
		The drop assembly appears to be installed correctly and draining properly.
		The crew is setting up to do the pressure test on the line.

Comments: