CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20190563

Address: 1809 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Jason McRoy Failed Monday, March 18,

Residential 2019

Corrective Action Required:

1 Misc 1. fire block soffit fir down space from stud spaces on east wall.

2. fire block entertainment built ins space from joist space above from end to

end.

3.install combustion air grates in wall adjacent to furnace room.

Comments: